ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0232, W0234, W0238	NA	MEDARAHALLI AREA
Segment No.	**Total Length (m)**	
12/S-W0232/S075912	344.39	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	113.18	77.515659	13.071638	77.516622	13.071243	W0309	W0301
2	126.69	77.515487	13.071410	77.516555	13.070945	W0309	W0301
3	104.52	77.515930	13.071834	77.516815	13.071460	W0309	W0301

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
ASPHALTING AND IMPROVEMENT TO CROSS ROADS AT MEDARAHALLI AREA	4500000	2017
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	ASPHALTING	012-16-000017
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/PACKAGE/WO/77/2016-17//17	03/10/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/10/2016	02/07/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SRI MURALISWAMY		0.00
Phone No.	**E-Mail ID**	
9243188999		

Paul. N.K.

Zone: DASARAHALLI Ward No: 12 Ward Name: Shettihalli Street ID: W0232, W0234, W0238

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Ravi

Date of Inspection

05/06/2017

Remarks

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SOMSHEKAR	05/06/2017	05/07/2017	COMPLETED
EE	SHESHADRI	05/06/2017	05/07/2017	COMPLETED
AEE	JAYALINGAPPA	05/06/2017	05/07/2017	COMPLETED
AE	RAVI	05/06/2017	05/07/2017	COMPLETED
AE	RAVI	05/06/2017	05/07/2017	COMPLETED

Zone: DASARAHALLI

Ward No: 12

Ward Name: Shettihalli

Street ID: W0232, W0234, W0238

ಸಹಾಯಕ ಆಯುಕ್ತರು ಮಂತರವು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0817, W0815, W0819, W0821	NA	KEREKALLU AREA
Segment No.	**Total Length (m)**	
12/S-W0817/S075243	336.86	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	58.06	77.514327	13.067076	77.514255	13.066556	W0772	DE
2	88.89	77.514094	13.067411	77.513989	13.066614	W0772	DE
3	94.81	77.513552	13.067450	77.513434	13.066601	W0772	DE
4	95.10	77.513834	13.067400	77.513716	13.066548	W0772	DE

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
ASPHALTING AND IMPROVEMENT TO ROADS AT KEREKALLU AREA	3500000	2017
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	ASPHALTING WOIRK	012-16-000020
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/PACKAGE/WO/77/2016-17\\20	03/10/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/10/2016	02/07/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SHRI MURALISWAMY		0.00
Phone No.	**E-Mail ID**	
9243188999		

Zone: DASARAHALLI Ward No: 12 Ward Name: Shettihalli Street ID: W0817, W0815, W0819, W0821

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಕೆಂಪಮ್ಮ ದೇವಸ್ಥಾನ ವಾರ್ಡ್ ಮತ್ತು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಪಿ.ಎಂ. ಬ್ಲಾಕ್, ರಾಜೇಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Ravi
Date of Inspection	**Remarks**	
05/06/2017		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SOMSHEKAR	05/06/2017	05/07/2017	COMPLETED
EE	SHESHADRI	05/06/2017	05/07/2017	COMPLETED
AEE	JAYALINGAPPA	05/06/2017	05/07/2017	COMPLETED
AE	RAVI	05/06/2017	05/07/2017	COMPLETED
AE	RAVI	05/06/2017	05/07/2017	COMPLETED

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0817, W0815, W0819, W0821

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0483, W0495, W0497, W0491, W0485	NA, Doddenakundi Indstrial Rd	RAGHAVENDRA LYT
Segment No.	**Total Length (m)**	
12/S-W0483/S074239	466.20	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	144.28	77.524056	13.067390	77.523759	13.066119	W0344	DE
2	58.39	77.523139	13.066867	77.523002	13.066356	W0344	DE
3	141.84	77.523710	13.067401	77.523406	13.066154	W0344	DE
4	121.69	77.523174	13.066268	77.523480	13.067327	W0344	DE

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
ASPHALTING AND IMPROVEMENTS TO CROSS ROADS IN RAGHAVENDRA LAYOUT AT KAMMAGONDANAHALLI AREA	7000000	2017
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	ASPHALTING WORK	012-16-000018
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/PACKAGE/WO/77/2016-17	03/10/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/10/2016	02/07/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SRI MURALISWAMY		0.00
Phone No.	**E-Mail ID**	

Zone: DASARAHALLI Ward No: 12 Ward Name: Shettihalli Street ID: W0483, W0495, W0497, W0491,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

9243188999

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Ravi
Date of Inspection	**Remarks**	
05/06/2017		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SOMSHEKAR	05/06/2017	05/07/2017	COMPLETED
EE	SHESHADRI	05/06/2017	05/07/2017	COMPLETED
AEE	JAYALINGAPPA	05/06/2017	05/07/2017	COMPLETED
AE	RAVI	05/06/2017	05/07/2017	COMPLETED
AE	RAVI	05/06/2017	05/07/2017	COMPLETED

Zone: DASARAHALLI Ward No: 12 Ward Name: Shettihalli Street ID: W0483, W0495, W0497, W0491,

Scanned by CamScanner